ECS/EMD Configuration Change Request					Page 1 of	Pag	ge(s)
1. Originator	2. Log Date:	3. CCR #:	4	4. Rev:	5. Tel:	6. Rm #:	7. Org.
Alexander Schuster	5/3/04	04-0240		_	925-0519	3008B	COTS SW
8. CCR Title: Install Irix 6.5.22 plus patches in PVC and VATC							
9. Originator Signature/Date			10. Cla	10. Class 11. Typ		12. Need Date: 05/06/04	
A. Schuster /s/ 4/30/04			11	II CCR			
13. CCR Sponsor Signature/Date			14. Category o		CII : DI 1 0=1		
Pamela Johnson /s/ 4/30/04				Update ECS/EMD Baseline Doc fill in Block 27). Routine			
9 , ,				hedule 18. CI(s) Affected: t:			
19. Release Affected by this Change: 20. Date due			to Customer: 21. Estimated Cost:				
7.00+ N/A			None - Under 100K				
22. Source Reference: ☐NCR (attach) ☐Action Item ☐Tech Ref. ☐GSFC ☑Other: EMD COTS Deployment Plan, Volume 1 P3 tasks: E1CTSWE060, E1CTINF276							
23. Problem: (use additional Sheets if necessary) SGI continually issues new Irix maintenance releases to fix bugs and improve overall system performance. EMD needs to deploy them to the sites periodically to mitigate operational risks. In addition, new Irix patches are needed to support other COTS software and hardware products. The upgrade and patches must undergo regression testing in the VATC and PVC before they can be released for all SGI machines at the DAACs.							
24. Proposed Solution: (use additional sheets if necessary) Install Irix 6.5.22 and other, supplemental patches on hosts p0acg05, p0console1, p0dig06, p0drg01, p0drg04, p0icg01, p0spg01, p0spg07, p0teg01, and ptdrg03, t1acg02, t1acg04, t1console1, t1dpg06, t1drg03, and t1spg03. (Patch list is attached, which includes newer patches for SPG machines already at Irix 6.5.22.) Use the attached installation instructions and return redlines to COTS SW Maint. No license keys are required.							
25. Alternate Solution: (use additional sheets if necessary) None							
26. Consequences if Change(s) are not approved: (use additional sheets if necessary) We would have to use some other machines for patch upgrade regression testing, or forego testing the patches in PVC and VATC as per the standard COTS upgrade process.							
27. Justification for Emergency (If Block 15 is "Emergency"):							
28. Site(s) Affected: DEDF DEDC DEDC DEDC DEDC DEDC DEDC DEDC							
29. Board Comments:				30. V	Nork Assigned T	o: 31. CCR (Closed Date:
32. SCDV CCB Chair (Sign	/Date):	Disposition: A	pproved	App/Co	om. Disapproved	Withdraw Fw	d/ESDIS ERB
Byron V. Peters /s/ 5			vd/ECS				
33. EDF CCB Chair (Sign/D	ate):	Disposition: Ap		App/Co	m. Disapproved	Withdraw Fwo	J/ESDIS ERB
, 3	-		wd/ECS				
34. ECS CCB Chair (Sign/D	4. ECS CCB Chair (Sign/Date): Disposition: Approved App/Com. Disapproved Withdraw Fwd/ESDIS ERE						
		Fwd/ESDIS					

CM01JA00 Revised 10/2/03 ECS/EDF/SCDV

ADDITIONAL SHEET

CCR #: 04-0240 Rev: — Originator: Alexander Schuster

Telephone: 301-925-0519 **Office:** COTS SW Maint.

Title of Change: Install Irix 6.5.22 plus patches in PVC and VATC

Block 16. Documentation/Drawings Impacted:

911-TDA-009 920-TDP-002 920-TDV-002 920-TDP-014 920-TDV-014

CM01AJA00 Revised 10/2/03 ECS/EMD